IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DGQ
Release Version	3.1b ME: 3.1.3.72
Release Date	5/24/2019
Previous Version	3.1a
Update Category	Recommended
Dependencies Dependencies	None
Important Notes	N/A
Enhancements	 Changed BIOS revision to 3.1b. Updated Intel microcode 0x43 for Haswell-EP and 0x36 for Broadwell-EP to address Intel-SA-00233 security issue. Updated Intel SPS firmware to E5_03.01.03.072.0_WBG_REL to address Intel-SA-00213 security issue.
New features	N/A
Fixes	1. Updated RSTe SATA/sSATA driver to v6.1.0.1017. 2. Updated ASPEED VBIOS to version 1.09.00.

Release Notes from Previous Release(s)

3.1a (4/17/2019)

- 1. Changed BIOS version to 3.1a.
- 2. Updated VBIOS from 0.96.0 to 1.03.01.

3.1 (6/11/2018)

- 1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.
- 2. Changed BIOS version to 3.1.
- 3. Set Descriptor Region of BIOS Region Write Access to "No".

3.0a (2/15/2018)

- 1. Implemented enhancement to address 'Spectre' variant 2 (CVE 2017-5715) security patch issue.
- 2. Updated RC to 4.3.0.
- 3. Changed BIOS revision to 3.0a.