## **BIOS Notes Release**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| Product Name            | X10QBi  |
|-------------------------|---|
| Release Version         | 3.2   |
| Release Date            | 5/31/2019   |
| <b>Previous Version</b> | 3.1   |
| <b>Update Category</b>  | Recommended   |
| Dependencies            | None  |
| Important Notes         | None  |
| Enhancements            | <ol> <li>Changed BIOS revision to 3.2.</li> <li>Updated Intel microcode 0x715 for IvyBridge-EX, 0x14 for Haswell-EX, and 0x36 for Broadwell-EX to address Intel-SA-00233 security issue.</li> </ol> |
| New features            | N/A   |
| Fixes                   | N/A   |

## Release Notes from Previous Release(s)

## 3.1 (6/12/2018)

1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.

## 3.0b (3/20/2018)

- 1. Changed BIOS revision to 3.0b.
- 2. Updated Intel Xeon microcode for Broadwell-EX Rev 2A for Intel Xeon E7-xxxx V4.
- 3. Updated Intel Xeon microcode for Haswell-EX Rev 11 for Intel Xeon E7-xxxx V3.