BIOS Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	B11DPT
Release Version	3.1
Release Date	5/29/2019
Previous Version	3.0a
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Changed BIOS version to 3.1.
	2. Updated the Leaky Bucket to 2.15 minutes at 2666MHz.
	3. Set SDDC+1 to disabled by default.
	4. Updated Intel RSTe to 6.1.0.1017.
	5. Updated Intel RC to ww16.
	6. Updated Hyper Threading and VMC default settings.
	7. Updated memory error log fru_text.
	8. Updated the Memory Correctable Threshold to 512.
	9. Set Leaky Bucket to 41.24 minutes with DDR speed at 2666MHz.
	10. Set ADDDC/SDDC to enabled by default.
	11. Updated Intel RC to ww12.
	12. Set PCIe hot plug to enabled by default.
	13. Updated LAN firmware to version 3.45
	14. Updated VM of M.2 AOM.
	15. Updated extended type 17.
	16. Updated RC to ww08.
	17. Merged 16 records of DMI type to a single record.
New features	N/A
Fixes	N/A