

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRW-I / IT
Release Version	3.84
Release Date	8/30/2019
Previous Version	3.80
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	<ol style="list-style-type: none">1. Fix Supermicro BMC Virtual Media Multiple Vulnerabilities.2. Corrected sensor readings after sort.3. Populated NAS-Identifier (rfc2865, 5.32.0) with BMC-specific string.4. Remove SEL showing error message after AOC-S3108 updates firmware.5. Log multiple absent HDDs as a StorageController event to remind user about possible component-related problem (e.g., storage controller, cable, or backplane error).